


Product Recall Notice

QP-2000 Digitech Power Point and Leakage Tester

Defect

Electus Distribution Pty Ltd is conducting a voluntary consumer level recall on the above product due to incorrect markings on the product and packaging. The product displays incorrect polarisation markings for the indicator lamps, and incorrect wiring identifications on the product and packaging. This could lead to incorrect diagnosis of a wiring fault.

In the interest of public safety, Electus is conducting a voluntary recall of all affected products.



Model Affected

Some earlier versions of the QP-2000 Digitech Power Point and Leakage Tester are affected by this issue.

Any units sold since May 2011 are not affected.

To identify an affected unit, the front of the case of the unit will have polarity markings (L-E, L-N, N-E) next to the indicator lamps. Refer to the picture left.



Unaffected models have different markings which do not show the polarity, as seen in the picture left, and have a different packaging to affected units. Packaging of unaffected units is shown right.



What to do

Consumers should stop using the affected product immediately, and contact their place of purchase or Electus Distribution to confirm if they have an affected unit and arrange a replacement.

All affected models will be replaced with an unaffected unit at no cost to the consumer.

Contact details

Electus Distribution Pty Ltd

Telephone: 1300 738 555

Fax: 1300 738 500

Email: sales@electusdistribution.com.au

Website: www.electusdistribution.com.au